

Die #	"AC	"AR	Teeth	#AC	#AR	Gap AC	Gap AR	Corners
C -.4375	7/16		48	4	12	1/16	1/16	
C -.625	5/8		48	3	8	1/8	1/8	
C -.75 CA	3/4		42	4	6	1/8	1/8	
C -.8125	13/16		40	4	5	1/8	3/16	
C -1A	1		55	4	6	1/8	7/48	
C -1B	1		54	3	6	1/8	1/8	
C -1C CA	1		57	4	6	1/8	3/16	
C -1F** Flex Die	1		88	6	9	1/8	.2222	
C -1.25	1 1/4		55	3	5	1/8	1/8	
C -1.25b CA	1 1/4		66	4	6	1/8	1/8	
C -1.25F Flex Die	1 1/4		88	5	8	1/8	1/8	
C -1.5	1 1/2		52	2	4	1/8	1/8	
C -1.625	1 5/8		56	2	4	1/8	1/8	
C -1.75	1 3/4		60	3	4	1/8	1/8	
C -1.875	1 7/8		48	1	3	—	1/8	
C -1.875	1 7/8		48	2	3	1/8	1/8	
C -1.875	1 7/8		48	3	3	1/8	1/8	
C -2	2		51	2	3	1/8	1/8	
C -2.125	2 1/8		54	2	3	1/8	1/8	
C -2.5A	2 1/2		43	1	2	—	3/16	
C -2.5B	2 1/2		63	2	3	1/8	1/8	
C -2.875	2 7/8		48	1	2	—	1/8	
C -2.875	2 7/8		48	2	2	1/8	1/8	
C -3 CA	3		50	2	2	1/8	1/8	
C -3.375*	3 3/8		56	2	2	1/8	1/8	
C -3.437	3 7/16		56	1	2	—	1/16	
C -3.5	3 1/2		58	1	2	—	1/8	
C -3.625	3 5/8		60	1	2	—	1/8	
C -3.75A	3 3/4		64	1	2	—	1/4	
C -3.75B CA	3.75		62	1	2		1/8	
C -4	4		66	1	2	—	1/8	
C -4**	4		66	2	2	1/8	1/8	
C -4.375	4 3/8		72	1	2	—	1/8	
C -5.5	5 1/2		46	1	1	—	1/4	
C -5.875	5 7/8		48	1	1	—	1/8	
C -6.25	6 1/4		51	1	1		1/8	
C -6.25*	6 1/4		51	1	1		1/8	